

Paradigm Spine GmbH | Eisenbahnstraße 84 | DE 78573 Wurmlingen

Paradigm Spine GmbH Eisenbahnstraße 84 DE 78573 Wurmlingen

Phone +49 7461 96 35 99 0 Fax +49 7461 96 35 99 20 Mail info@paradigmspine.com

www.paradigmspine.com

FIELD SAFETY CORRECTIVE ACTION - RECALL

REC 2024-01

IMMEDIATE ACTION REQUIRED

Recipient:	Customers, Distributors and Sales Department				
Affected Product:	HPS 2.0 Rod coupler, S=25N/mm, 27mm				
Manufacturer	Paradigm Spine GmbH				
Date of Recall	17.07.2024				
Type of Recall	Field Safety Corrective Action (FSCA)				
Item, lot and UDI	Item Number	LOT Number	UDI Number		
number:	HBI92527	1321000344	(01)04260148891649(17)290731(10)1321000344		
	HBI92527	1321000352	(01)04260148891649(17)290731(10)1321000352		
	HBI92527	1322000026	(01)04260148891649(17)300430(10)1322000026		
	HBI92527	1322000072	(01)04260148891649(17)300531(10)1322000072		
	HBI92527	1322000073	(01)04260148891649(17)300531(10)1322000073		
	HBI92527	1322000074	(01)04260148891649(17)300531(10)1322000074		
	HBI92527	1322000075	(01)04260148891649(17)300630(10)1322000075		
Reason for FSCA	It has been determined that the internal thread of the rod coupler within the specified batches				
	was manufactured out of the specified tolerances. This may result in the corresponding rod not				
	being able to be fully screwed in.				
Clinical Effect	If the case described above occurs, the surgery may be delayed until the defective rod coupler				
	has been replaced. If no replacement is available, it is necessary to deviate from the planned				
	procedure and perform a fusion.				
Action Required	We would like you to identify all affected products in your warehouse as well as in your field				
	inventory in the hospitals and return them immediately for inspection and quarantine. These				
	items must not be sold or used. Please fill in the attached form to confirm that you have				
	inspected your inventory and that the affected parts will be returned or have been already				
	used.				
Transmission of this	This notice needs to be passed on to all those who need to be aware within your organization				
Recall	or to any organization where the potentially affected devices have been transferred (If				
	appropriate).				
	appropriates.				



Further Information For further questions related to this Field Safety Corrective Action (FSCA) do not hesitate to

contact our customer sales department at:

Paradigm Spine GmbH Eisenbahnstraße 84

78573 Wurmlingen / Germany psg-service@paradigmspine.com

Tel.: +49(0)7461 963599-0

We deeply regret the inconvenience and will take all possible corrective and preventive action to avoid this in the future. We appreciate your quick response, your cooperation and your understanding.

CONFIRMATION OF RECEIPT

Please sign and return to Paradigm Spine GmbH

I hereby confirm that I have received this Notice.		
Date:		
Signature:		



Confirmation of Inventory

Please return this form to Paradigm Spine by fax or email.

Fax: +49(0)7461 963599-20 / Email: psg-service@paradigmspine.com

According to our traceability records you have received items of the recalled lots. Please check your inventory and your accounts in your territory.

Item number	Lot number	Qty.	Delivery date	In inventory or accounts yes/no	Will be returned yes/no	Already implanted yes/no

Please complete the table above and sign below to confirm that you checked your inventory, your accounts in your territory and that you informed your customers, if applicable.

Company:	
Print Name:	
Signature:	
Position/title:	
Date:	



Please send the affected items separately (not mixed with other products) to the following address using recall number REC 2024-01.

Paradigm Spine GmbH
Eisenbahnstraße 84
78573 Wurmlingen
Germany
Attn: QA Department / Recall 2024-01

You will receive replacement implants immediately.

