



STATYBOS PRODUKCIJOS
SERTIFIKAVIMO CENTRAS

PERFORMANCE RESULTS

Ösel Plastic OÜ

Talli str. 3 Kuressaare city, Saaremaa vald, Saare maakond 93815, Estonia

EN 12566-1:2000, EN 12566-1:2000/A1:2003

“Small wastewater treatment systems for up to 50 PT”

**Small wastewater treatment system
ÖSEL SEPTIC 2500**

Material

Polyethylene

Watertightness
(water test)

pass

Performance tested by:

SPSC - Statybos produkcijos sertifikavimo centras

Linkmenų str. 28

LT-08217 Vilnius

Lithuania

Notified Body number: 1397

Director Valdemaras Gauronskis

May 2022

Reg. Nr. 58_2022

This document replaces neither the declaration of performance nor CE marking



STATYBOS PRODUKCIJOS
SERTIFIKAVIMO CENTRAS

PERFORMANCE RESULTS

Ösel Plastic OÜ

Talli str. 3 Kuressaare city, Saaremaa vald , Saare maakond 93815 , Estonia

EN 12566-1:2000, EN 12566-1:2000/A1:2003

“Small wastewater treatment systems for up to 50 PT”

**Small wastewater treatment system
ÖSEL SEPTIC 2000**

Material

Polyethylene

Watertightness
(water test)

pass

Hydraulic efficiency

14,42 g collected beads

Performance tested by:

SPSC - Statybos produkcijos sertifikavimo centras

Linkmenų str. 28

LT-08217 Vilnius

Lithuania

Notified Body number: 1397

Director Valdemaras Gauronskis

May 2022

Reg. Nr. 58_2022

This document replaces neither the declaration of performance nor CE marking



STATYBOS PRODUKCIJOS
SERTIFIKAVIMO CENTRAS

PERFORMANCE RESULTS

Ösel Plastic OÜ

Talli str. 3 Kuressaare city, Saaremaa vald, Saare maakond 93815, Estonia

EN 12566-1:2000, EN 12566-1:2000/A1:2003

“Small wastewater treatment systems for up to 50 PT”

Small wastewater treatment system

ÖSEL SEPTIC 3000

Material	Polyethylene
Watertightness (water test)	pass
Structural behavior (pit test, conditions: WET 1,0 m)	pass

Performance tested by:
SPSC - Statybos produkcijos sertifikavimo centras
Linkmenų str. 28
LT-08217 Vilnius
Lithuania

Notified Body number: 1397

Director Valdemaras Gauronskis

May 2022

Reg. Nr. 57_2022

This document replaces neither the declaration of performance nor CE marking